



**Weidmüller** 

## **Experience with De-icing systems, noise and vibrations evoked by ice accretion**

Dr. Daniel Brenner, [Daniel.Brenner@Weidmueller.com](mailto:Daniel.Brenner@Weidmueller.com)


Skellefteå, Winterwind conference, 08<sup>th</sup> Feb 2017

- Where does the experience come from?
- De-icing systems
- Noise
- Vibrations




## System facts summary

- **Turbines in Monitoring: >1,500\***
- **Sold Systems, in total: >2,000\***
- **Monitoring background**
  - Over 4,000\* machine years of monitoring experience
- **Market distribution**
  - System of choice of all major OEMs and large operators
  - Covering a wide variety of turbine and blade types, on- and offshore
- **BLADEcontrol is the pioneer in rotor blade monitoring**
  - Ice detector first certified in 2008
  - Damage detection first certified in 2013




\* as of February 1<sup>st</sup>, 2017


## Icing only on leading edge




## Ice rain on whole turbine and blade



## Trailing edge icing esp. at serrations




Source: [windpowerengineering.com](http://windpowerengineering.com)



- All natural oscillations decrease due to ice
  - Blades natural frequencies as well as whole rotor natural frequencies

Icing event with over 250 kg ice per blade

## Visualization of ice accretion over time



ice accretion plotted as blue line:


- Icing trend proportional to amount of ice
- Green area means „free of ice“
- Yellow – warning
- Red area – heavy ice accretion -> usually turbine stop necessary

## Hot air fan

6 turbines with De-icing equipped with BLADEcontrol

Icing duration this season: 140 hours per turbine

Heating events this season: > 20 per turbine




**conclusion:** Hot air fan is a robust system / technique, capable of de-icing

**De-icing system:** heating mat on leading edge of the outer 2 third of the blade

Recalibration of BLADEcontrol after De-icing system installation necessary

**Heating mat separated partly and was deinstalled before winter season**




**BLADEcontrol** damage detection indicator revealed defect at heating mat at blade 2 (blue)

**conclusion:** Proof of reliability for systems with heating mat on leading edge necessary



# Tonality – excited by drive train



**Noise reduced mode**  
**Lower rotor speed** for  
 lower blade tip speed,  
 but **maximum torque**  
 for high power output

**For this Turbine**  
 Decreasing noise  
 strategy led to Tonality  
 -> increased noise


**Complaints by residents:**  
 sounds like a starting helicopter

**Influence of icing:** Reduction of vibration frequency shifts the tonality problem to a different rotor speed

## Icing at trailing edge especially at serrations

Complaints by residents near windfarms about whistling sound

Investigation by technicians on the turbine: very thin icing between teeth of serrations




Source: [windpowerengineering.com](http://windpowerengineering.com)

### **For this Incident**


Decreasing noise strategy led to whistling sound -> increased noise

## Detection of increased Drive Train Torsion



Amplitude of the drive train torsion vibration measured on the blades plotted over wind speed

Noticable measurement triggers information for manufacturer




Reduction of the vibration via controller adaption

After correction by manufacturer

**Influence of icing:**  
Reduction of vibration may not be adjusted by open-loop controller

## Example: Small aerodynamic imbalance excites tower vibration



Only little icing, below 50 % of alarm value

Acceleration sensor in nacelle triggers turbine stop

### Hybrid tower

height: 140m

1<sup>st</sup> natural tower vibration: 0.15 Hz

Rotor speed : 0.15 Hz (9 rpm)

Rotor speed = natural tower vibration

+ small imbalance

-> **RESONANCE**

## Summary

- De-icing solutions differ in maturity
- Noise by thin ice between serrations difficult to detect an de-ice
- Natural Vibration frequency changes due to ice accretion -> may lead to resonance
- Aerodynamic imbalance + rotor running with tower vibration frequency causes emergency stops

